LV1b imu-analog
board mechanical
drawing

v

ω_v

a_v

a_u

(0,0)

w

ω_w

u

(-1.11,0.385)

(-0.69,0)

(-0.234,-0.719)

a_w

a_{uv}

ω_u

(0.270,-0.960)

accelerometer arrows indicate the sensitive axis in the direction of positive output
gyro arrows indicate the sensitive axis, positive output follows the right hand rule
circles indicate the sensitive axis is up out of the plane of the drawing