



**PSU AESSE
LV1b IMU Analog board
Rev. 1.5 8/14/00**

All OP-Amps 1/2 LT1013

Note 1:
Locate Filter near ADC rather than sensor

Not Placed: 0.1 bypass capacitors
C9, C466, 407, C508, C606, 607, C709, C806